



Repair Shop:
Phone Number:
Address:

Report Number: MAXIA20211227
Creation Date: 2021-12-27



DETROIT Vehicle Diagnostic Report

License Plate: TTTGG
Manufacturer: DETROIT
Year:
Model:
Sub Model:
Engine:
Path: DETROIT>Control unit>Common Powertrain Controller EPA10(CPC02T)>Trouble codes

Client:
Phone Number:
VIN:
Mileage:
Color:
Status:

Trouble codes

Codes	Description	Status
SPN 973 FMI 13	SAE J1939 engine retarder selection signal missing or unavailable	Active
SPN 3696 FMI 13	Diesel Particulate Filter (DPF) regeneration force MUX switch message containing SNV indicator	Active
SPN 111 FMI 3	Coolant level circuit voltage high	Inactive