## ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HIS	STORY RECORD
REPORT NUMBER	FLEET UNIT NUMBER
DATE 5-16-20	23

3 10 0023		
INSPECTOR'S NAME (PRINT OR TYPE)		
Hows 1. Fr.72		
THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.		
<b>™</b> YES		
VEHICLE IDENTIFICATION (► AND COMPLETE) ☐ LIC. PLATE NO. VIN ☐ OTHER		
1 FUBC 5 DV 6 D HFG 7153		
INSPECTION AGENCY/LOCATION (OPTIONAL)		

K NEEDS REPAIRED DATE	ITEM	OK NEEDS REPAIRED DATE	ITEM	OK NEEDS REPAIRED DATE	ITEM
1	1. BRAKE SYSTEM	UNICEMENT UNIC		OT HEPAIR DATE	
A A A	<ul> <li>a. Service Brakes</li> <li>b. Parking Brake System</li> <li>c. Brake Drums or Rotors</li> <li>d. Brake Hose</li> <li>e. Brake Tubing</li> <li>f. Low Pressure Warning Device</li> <li>g. Tractor Protection Valve</li> <li>h. Air Compressor</li> <li>i. Electric Brakes</li> <li>j. Hydraulic Brakes</li> </ul>	J NA	a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.  b. Protection against shifting cargo.  c. Container securement devices on intermodal equipment.  7. STEERING MECHANISM	JU/A J/A	a. Tires on any steering axis of a power unit. b. All other tires. c. Installation of speed-restricted tires unless specifically designated by motor carrier.  11. WHEELS AND RIMS a. Lock or Side Ring b. Wheels and Rims c. Fasteners
V/A V/A V/A	k. Vacuum Systems I. Antilock Brake System m. Automatic Brake Adjusters  2. COUPLING DEVICES a. Fifth Wheels b. Pintle Hooks c. Drawbar/Towbar Eye d. Drawbar/Towbar Tongue e. Safety Devices f. Saddle-Mounts  3. EXHAUST SYSTEM a. Exhaust system leaking forward of or directly below the driver/sleeper		a. Steering Wheel Free Play b. Steering Column c. Front Axle Beam and All Steering Components Other Than Steering Column d. Steering Gear Box e. Pitman Arm f. Power Steering g. Ball and Socket Joints h. Tie Rods and Drag Links i. Nuts j. Steering System 8. SUSPENSION		d. Welds  12. WINDSHIELD GLAZING  Requirements and exception as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).  13. WINDSHIELD WIPERS  Any power unit that has an inoperative wiper, or missing or damaged parts that rende it ineffective.  14. MOTORCOACH SEATS  Any passenger seat that is
	compartment.  b. Bus exhaust system leaking or discharging in violation of standard.  c. Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle.  4. FUEL SYSTEM  a. Visible leak. b. Fuel tank filler cap missing. c. Fuel tank securely attached.  5. LIGHTING DEVICES  All lighting devices and reflectors required by Part 393 shall be operable.	J J NA	a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position. b. Spring Assembly c. Torque, Radius or Tracking Components  9. FRAME a. Frame Members b. Tire and Wheel Clearance c. Adjustable Axle Assemblies (Sliding Subframes)		not securely fastened to the vehicle structure.  15. OTHER  List any other condition(s) which may prevent safe operation of this vehicle.

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.